

FIG. 1

Title: DIRECT DETECTION OF COIL RESISTANCE
 Document No.: PANA-01077US0
 Inventor: Brian Tanner
 Serial No.: Unknown
 Attorney: Sheldon R. Meyer
 Phone: (415)362-3800
 Express Mail No.: EV326482135US
 Filed: Herewith
 Confidentiality No.: Unknown
 Attorney: Sheldon R. Meyer
 Phone: (415)362-3800
 Express Mail No.: EV326482135US
 Sheet 1 of 5




FIG. 2A

Title: DIRECT DETECTION OF COIL RESISTANCE	Document No.: PANA-01077US0	Imprintor: Brian Tanner
Filed: Herewith	Confirmation No.: Unknown	Express Mail No.: EV326482135US
Serial No.: Unknown	Attorney: Sheldon R. Meyer	Phone: (415)362-3800




FIG. 2B

Title: DIRECT DETECTION OF COIL RESISTANCE
Doc#: PANA-01077US0 Inventor: Brian Tanner
Serial No.: Unknown Author: Sheldon R. Meyer
Phone: (415)362-3800 Express Mail No.: EV326482135US
Filed: Herewith Confirmation No.: Unknown
Fax#: (415)362-3800




FIG. 3

Title: DIRECT DETECTION OF COIL RESISTANCE
 Document No.: PANA-01077US0 Serial No.: Unknown
 Inventor: Brian Tanner Attorney: Sheldon R. Meyer
 Confirmation No.: Unknown Phone: (415)362-3800
 Filed: Herewith Express Mail No.: EV326482135US
 Sheet 4 of 5




FIG. 4

Title: DIRECT DETECTION OF COIL RESISTANCE
 Doc#: PANA-01077US0 Inventor: Brian Tanner
 Serial No.: Unknown Attorney: Sheldon R. Meyer
 Confirmation No.: Unknown Phone: (415) 362-3800
 Filed: Herewith Express Mail No.: EV326482135US
 Sheet 5 of 5